



NOTES:

1. OVER EXCAVATION REQUIRED WHEN UNSUITABLE FOUNDATION MATERIALS ENCOUNTERED.
2. STRICTLY COMPLY WITH ALL TRENCH SAFETY SYSTEM REQUIREMENTS.
3. RESTRAINED JOINT PIPE MAY BE REQUIRED AS DIRECTED BY THE DISTRICT.
4. BACKFILL TRENCH IN ACCORDANCE WITH DIVISION 7 AND TBR-1.



**UNSUITABLE FOUNDATION
EXCAVATION**

DATE: 11-2015

DWG. TBR-3

APPROVED BY: DLH
DISTRICT ENGINEER