

Burlington, WA Corporate Laboratory (a) 1620 S Walnut SI - Burlington, WA 98233 - 800.755.9295 • 360.757.1400

Bellingham, WA Microbiology (b)

Portland, OR Microbiology/Chemistry (c) 9725 SW Commerce Cr Ste A2 - Wilsonville, OR 97070 - 503.682.7802

Corvallis, OR Microbiology/Chemistry (d) 1100 NE Circle Blvd, Ste 130 - Corvallis, OR 97330 - 541.753.4946 Bend, OR *Microbiology* (e) 20332 Empire Blvd Ste 4 - Bend, OR 97701 - 541.639.8425



Page 1 of 1

Washington State Department of Health WATER BACTERIOLOGICAL ANALYSIS

Client Name: Alderwood Water District

3626 156th Street SW

Lynnwood, WA 98087

System Name: 164TH ST ARTESIAN WELL

System ID Number: 01319B

DOH Source Number: 00 - Distribution Sample (Bacteria)

Sample Type: D - Drinking Water Sample Purpose: C - Compliance

Sample Location: 2411 164th St SW (Artesian Well #5)

County: Snohomish Sampled By: AWWD

Sampler Phone:

Reference Number: 24-30622

Project: Bacteria

Repeat Sample Number:

Lab Number: 164-58891

Field ID: 2910

Date Collected: 10/7/24 09:36

Date Received: 10/8/24

Date Set: 10/8/24 13:28 Date Analyzed: 10/9/24 11:09 Report Date: 10/11/24 Comment: Cl2: 0.0.

Approved By: ckk,mlp

Authorized by:

Lab Manager, Bellingham

DOH#	PARAMETER	RESULT	Qualifier	UNITS	Analyst	METHOD	Batch	COMMENT
1	TOTAL COLIFORM	Satisfactory, Coliforms Absent		per 100mL	mlh	SM9223 B	m_241008a	
3	E. COLI	Absent		per 100mL		SM9223 B	m_241008a	

If the sample is unsatisfactory you can get information on well disinfection at Washington State Department of Health:

WA DOH: https://doh.wa.gov/community-and-environment/drinking-water/disinfection

NOTES: